




Inspection Analysis



Ray Moss, Agent
P: 800.596.8782
E: rmos@navigatortruckinsurance.com

UNITED ROAD FREIGHT INC
DOT # 3660044

Current BASIC Scores




Primary Score Contributors


Across All Categories

VIN	Year	Make	License	% of Total Score	Violations
4V4NC9GH75N390591	2005	Volvo Truck	P1089909	16%	x10
5AXCG40261R174224	2001	Armor Chassis	3417637	15%	x3
3H3C242S4MT200128	2021	Hyundai Translead ...	U225916	10%	x4
4V4NC9TG86N386354	2006	Volvo Truck	P1067891	9%	x4
4V4NC9GH26N419836	2006	Volvo Truck	P1016378	9%	x3
1XPHD49X7DD213345	2013	Peterbilt	P983132	9%	x4
1FTWW33R88ED93121	2008	Ford	508742D	8%	x2
1XKWD29X1VR734289	1997	Kenworth	P1139635	5%	x2


BASIC Scores



New Points (previous 90 days)



Expiring Points (next 90 days)



FMCSA Snapshot



Top Score Contributors: This insight helps identify equipment and drivers that contribute the most points toward CSA scores. It can assist you with determining specific maintenance issues like brakes, lighting and tires, or consistent driver issues like inaccurate logs, speeding or mobile device use.

Top 5 Driver Score Contributors

VIN	Year	Make	License	% of Driver Score	Violations	Unsafe Driving	HOS	Controlled Sub.	Drv. Fit.	Driver Points
1FTWW33R88ED93121 △	2008	Ford	508742D	8%	x2	0+0+	0+	0+	33=	33
4V4NC9GH75N390591 △	2005	Volvo Truck	P1089909	6%	x4	25+0+	0+	0+	0=	25
1XPHD49X7DD213345 △	2013	Peterbilt	P983132	5%	x2	10+10+	0+	0+	0=	20
4V4NC9GH26N419836 △	2006	Volvo Truck	P1016378	4%	x1	0+15+	0+	0+	0=	15
4V4NC9TG86N386354 △	2006	Volvo Truck	P1067891	3%	x1	0+14+	0+	0+	0=	14

Top 5 Tractor Score Contributors

VIN	Year	Make	License	% of Tractor Score	Violations
4V4NC9GH75N390591 △	2005	Volvo Truck	P1089909	9%	x6
4V4NC9TG86N386354 △	2006	Volvo Truck	P1067891	6%	x3
4V4NC9GH26N419836 △	2006	Volvo Truck	P1016378	5%	x2
1XPHD49X7DD213345 △	2013	Peterbilt	P983132	4%	x2
1XKWD29X1VR734289 △	1997	Kenworth	P1139635	3%	x1


Top 5 Trailer Score Contributors

VIN	Year	Make	License	% of Trailer Score	Violations
5AXCG40261R174224 △	2001	Armor Chassis	3417637	15%	x3
3H3C242S4MT200128 △	2021	Hyundai Transl...	U225916	10%	x4
3H3C242S81T105521	2001	Hyundai Transl...	U189496	5%	x2
5JWDD1422NN554801	2022	H & H Trailers, ...	TEMP	4%	x1

Top Violations Breakdown: This insight helps identify what behaviors may be contributing to your CSA Violations. Whether it's Lights, Braking, Speeding or Form and Manner violations, you'll be able to tailor your safety program to address unique characteristics of your operation.


BASIC Score

UNSAFE DRIVING - 14%




Dangerous 48%

Dangerous Driving	100%
Reckless Driving	0%




Speeding 45%

Speed (6 - 10)	63%
Speed (11 - 14)	37%
Speed (15+/Work Zn)	0%
Other	0%




Driver Activity 0%

Phone Call	0%
Seat Belt	0%
Texting	0%



Other 7%

HM Related	0%
Other	100%




BASIC Score

HOURS OF SERVICE - 63%




Log 100%

False	0%
Incomplete/Wrong	100%




ELD 0%

Documentation	0%
Operator Error	0%
Installation	0%
Other	0%




Hours 0%

General	0%
Nominal	0%
OOS/Fatigue	0%




Other 0%

Form & Manner	0%
Other	0%



BASIC Score


VEHICLE MAINT. - 83%



Alert


Visibility 57%

Lighting	76%
Warning Flags	0%
Clearance Lamps/Other	11%
Reflective Sheeting	6%
Glass/Markings	7%




Brakes/Steering 22%

Brakes, OOS	0%
Brakes, Adjustment	0%
Brakes, Other	100%
Steering Mechanism	0%
Suspension	0%




Wheels 11%

Tires	100%
Wheels/Studs/Clamps	0%
Tire vs. Load	0%




Engine/Truck 6%

Fuel Systems	0%
Exhaust Discharge	0%
Cab Body Frame	0%
Other Vehicle Defect	100%




All percentages are rounded to the nearest whole number.


BASIC Score

DRIVER FITNESS - 0%

License 91%


High	100%
Medium	0%
Low	0%


Health 9%


Medical Certificate	100%
Physical	0%


Qualification 0%

General	0%
---------	----


Other 0%

Fraud	0%
Other	0%




BASIC Score


CONTROLLED SUB. - 0%

Alcohol 0%


Alcohol	0%
Possession	0%


Drugs 0%


Drugs	0%
-------	----


Jumping OOS 0%

Jumping OOS	0%
-------------	----


Other 0%

Other	0%
-------	----




BASIC Score

HAZMAT - 0%

Cargo 0%


Load Securement	0%
Cargo Protection	0%
Package Integrity	0%


Preventative 0%


Fire Hazard	0%
Package Testing	0%
Markings	0%


Route 0%

Wrong Route	0%
-------------	----


Other 0%

Documentation	0%
Other	0%



All percentages are rounded to the nearest whole number.



Recent Inspection Summary

No recent inspections in the past 30 days

Driver Violations

Most recent at top

	Added	Removal	VIN	Year	Make	Weight Severity × Time = Total	BASIC / Description	Report
🔴	11/10/22	11/10/24	1FTWW33R88ED93121	2008	Ford	10 × 3 = 30	Driver Fitness / License-related: High	4015
	11/10/22	11/10/24	1FTWW33R88ED93121	2008	Ford	1 × 3 = 3	Driver Fitness / Medical Certificate	4015
🟢	9/7/22	9/7/24	4V4NC9GH26N419836	2006	Volvo Truck	5 × 3 = 15	Hours of Service / Incomplete/Wrong Log	5675
🟢	6/7/22	6/7/24	4V4NC9GH75N390591	2005	Volvo Truck	4 × 2 = 8	Unsafe Driving / Speeding 2	0328
	4/18/22	4/18/24	4V4NC9TG86N386354	2006	Volvo Truck	7 × 2 = 14	Hours of Service / Incomplete/Wrong Log	3195
🟢	3/21/22	3/21/24	4V4NC9GH75N390591	2005	Volvo Truck	5 × 2 = 10	Unsafe Driving / Dangerous Driving	2082
🟢	2/24/22	2/24/24	1XPHD49X7DD213345	2013	Peterbilt	5 × 2 = 10	Unsafe Driving / Dangerous Driving	2677
🟢	2/24/22	2/24/24	1XPHD49X7DD213345	2013	Peterbilt	5 × 2 = 10	Hours of Service / Incomplete/Wrong Log	2677
🟢	2/18/22	2/18/24	1XKWD29X1VR734289	1997	Kenworth	5 × 2 = 10	Hours of Service / Incomplete/Wrong Log	3039
🟢	10/21/21	10/21/23	4V4NC9GH66N392320	2006	Volvo Truck	7 × 1 = 7	Unsafe Driving / Speeding 3	4283
	9/7/21	9/7/23	4V4NC9GH75N390591	2005	Volvo Truck	3 × 1 = 3	Unsafe Driving / Misc Violations	0069
	9/7/21	9/7/23	4V4NC9GH75N390591	2005	Volvo Truck	4 × 1 = 4	Unsafe Driving / Speeding 2	0069

Trailer Violations

Most recent at top

	Added	Removal	VIN	Year	Make	Weight Severity × Time = Total	BASIC / Description	Report
	11/10/22	11/10/24	5JWDD1422NN554801	2022	H & H Trailers, Llc.	6 × 3 = 18	Vehicle Maintenance / Brakes All Others	4015
	7/7/22	7/7/24	5AXCG40261R174224 	2001	Armor Chassis	10 × 3 = 30	Vehicle Maintenance / Tires	1577
	7/7/22	7/7/24	5AXCG40261R174224 	2001	Armor Chassis	2 × 3 = 6	Vehicle Maintenance / Clearance Identification Lamps/Other	1577
	7/7/22	7/7/24	5AXCG40261R174224 	2001	Armor Chassis	8 × 3 = 24	Vehicle Maintenance / Lighting	1577
	4/18/22	4/18/24	3H3C242S4MT200128 	2021	Hyundai Transle...	4 × 2 = 8	Vehicle Maintenance / Brakes All Others	3195
	4/18/22	4/18/24	3H3C242S4MT200128 	2021	Hyundai Transle...	2 × 2 = 4	Vehicle Maintenance / Clearance Identification Lamps/Other	3195
	4/18/22	4/18/24	3H3C242S4MT200128 	2021	Hyundai Transle...	8 × 2 = 16	Vehicle Maintenance / Lighting	3195
	4/18/22	4/18/24	3H3C242S4MT200128 	2021	Hyundai Transle...	6 × 2 = 12	Vehicle Maintenance / Lighting	3195
	2/24/22	2/24/24	3H3C242S81T105521	2001	Hyundai Transle...	2 × 2 = 4	Vehicle Maintenance / Clearance Identification Lamps/Other	2677
	2/24/22	2/24/24	3H3C242S81T105521	2001	Hyundai Transle...	8 × 2 = 16	Vehicle Maintenance / Lighting	2677

Tractor Violations

Most recent at top

	Added	Removal	VIN	Year	Make	Weight Severity × Time = Total	BASIC / Description	Report
⬆️	11/30/22	11/30/24	4V4NC9GH37N396990	2007	Volvo Truck	3 × 3 = 9	Vehicle Maintenance / Other Vehicle Defect	0453
⬆️	10/19/22	10/19/24	1M1AN07Y99N003609	2009	Mack	2 × 3 = 6	Vehicle Maintenance / Emergency Equipment	0596
⬇️	9/22/22	9/22/24	4V4NC9TG86N386354 ⬆️	2006	Volvo Truck	1 × 3 = 3	Vehicle Maintenance / Windshield/ Glass/ Markings	0544
⬇️	9/22/22	9/22/24	4V4NC9TG86N386354 ⬆️	2006	Volvo Truck	3 × 3 = 9	Vehicle Maintenance / Other Vehicle Defect	0544
⬇️	9/7/22	9/7/24	4V4NC9GH26N419836 ⬆️	2006	Volvo Truck	1 × 3 = 3	Vehicle Maintenance / Windshield/ Glass/ Markings	5675
⬇️	9/7/22	9/7/24	4V4NC9GH26N419836 ⬆️	2006	Volvo Truck	6 × 3 = 18	Vehicle Maintenance / Lighting	5675
⬇️	7/7/22	7/7/24	4V4NC9GH75N390591 ⬆️	2005	Volvo Truck	3 × 3 = 9	Vehicle Maintenance / Reflective Sheeting	1577
⬇️	7/7/22	7/7/24	4V4NC9GH75N390591 ⬆️	2005	Volvo Truck	1 × 3 = 3	Vehicle Maintenance / Windshield/ Glass/ Markings	1577
⬇️	7/7/22	7/7/24	4V4NC9GH75N390591 ⬆️	2005	Volvo Truck	4 × 3 = 12	Vehicle Maintenance / Brakes All Others	1577
	4/18/22	4/18/24	4V4NC9TG86N386354 ⬆️	2006	Volvo Truck	6 × 2 = 12	Vehicle Maintenance / Lighting	3195
⬇️	3/21/22	3/21/24	4V4NC9GH75N390591 ⬆️	2005	Volvo Truck	1 × 2 = 2	Vehicle Maintenance / Windshield/ Glass/ Markings	2082
⬇️	3/21/22	3/21/24	4V4NC9GH75N390591 ⬆️	2005	Volvo Truck	2 × 2 = 4	Vehicle Maintenance / Emergency Equipment	2082
⬇️	3/21/22	3/21/24	4V4NC9GH75N390591 ⬆️	2005	Volvo Truck	4 × 2 = 8	Vehicle Maintenance / Brakes All Others	2082
⬇️	2/24/22	2/24/24	1XPHD49X7DD213345 ⬆️	2013	Peterbilt	4 × 2 = 8	Vehicle Maintenance / Brakes All Others	2677
⬇️	2/24/22	2/24/24	1XPHD49X7DD213345 ⬆️	2013	Peterbilt	4 × 2 = 8	Vehicle Maintenance / Brakes All Others	2677
⬇️	2/18/22	2/18/24	1XKWD29X1VR734289 ⬆️	1997	Kenworth	6 × 2 = 12	Vehicle Maintenance / Lighting	3039

Clean Inspections

Most recent at top

Added	VIN	Year	Make	BASICS Assessed					
				 Hazmat	 Controlled Sub.	 Drv. Fit.	 Vehicle Maint.	 HOS	 Unsafe Driving
9/23/22	1FUJA6CK84LM77516	2004	Freightliner	n/a	✓	✓	n/a	✓	✓
7/7/22	4V4NC9GH37N396990	2007	Volvo Truck	n/a	✓	✓	n/a	✓	✓
3/15/22	3AKJGLD59ESFT6202	2014	Freightliner	n/a	✓	✓	n/a	✓	✓
9/24/21	4V4NC9GH75N390591 	2005	Volvo Truck	n/a	✓	✓	n/a	✓	✓